



JURGENSEN PUMP, LLC
PO Box 710
Valley Mills, TX 76689

Phone # 254-932-6251 Fax # 254-932-6770

Estimate

Date	Estimate #
9/14/2020	3735

REGULATED BY THE TEXAS
 DEPARTMENT OF LICENSING &
 REGULATIONS PO BOX 12157
 AUSTIN, TX 78711
 LICENSE #54576

Name / Address

City of Florence
 PO Box 430
 Florence, TX 76527

WARRANTY: New well equipment is covered by
 Manufacturer's Warranties and these warranties are
 the responsibility of the Manufacturers.
LABOR WARRANTY: Is 30-days from
 installation of new well equipment

Project

WWTP Lift Station

Description	Qty	Cost	Total
WWTP Lift Station 10HP / 3PH / 460V			
Field Service to Inspect Pumps 1 & 3. Pump #1 was pulled and inspected. It was found to be running backwards. Rotation was changed and the pump was reinstalled and started up. The pump ran good. Pump #3 was checked and the motor was grounded. The pump was loaded up and brought in for tear down and inspection. Note: Price includes labor and mileage	1	1,175.00	1,175.00
Tear Down and Inspection The volute was removed and the lower seal chamber oil was drained. Water was found to be in the seal chamber and also in the motor housing. This caused the motor stator to short out. Note: No charge for tear down if pump is repaired or replaced by Jurgensen Pump	1	0.00	0.00
Pump Repair to include the Following: Rewind the motor stator, replace upper and lower bearings, replace mechanical seals, replace o-rings, replace rubber grommet for power cord, fill seal chamber with oil, clean parts and assemble. New lifting chain also included. Lead Time ----- 2 to 3 Weeks	1	5,409.00	5,409.00
Flygt 3127.060 Model NP-3127.060 4" Submersible Pump with 4" Discharge, 10HP / 3PH / 460V Motor, 50' Power Cord and SST Lifting Chain Lead Time for New Pump is 2 to 3 Weeks	1	15,323.00	15,323.00
Quote valid for 30 days!		Subtotal	\$21,907.00
		Sales Tax (0.00)	\$0.00
		Total	\$21,907.00